

## **COMPLAINT INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	John McCutcheon
Inspection Date:	Wednesday, August 15, 2018	Project Contact:	Brian Clauto, Tracy Hilbun
Spread:	Spread I	Weather (Wet/Dry/Rain):	Dry

STA	GE OF CONSTRUCTION: (Check all that apply)		
$\boxtimes$	Clearing Rough Grading Trench Exca	avation	Pipe Assembly, Testing & Installation
	Backfilling and Grade Restoration Final Grading & Stabilizati	ion	Other:
		Yes No N/A	
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?		
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?		
3	Areas of offsite sediment deposition were observed?		
	omments: This report is for an inspection at Bent Mountain in Roanoke Courtable toilet located near a stream.  1. Portable toilet observed to be located well-away from stream.	nty on Bottom Cr	reek Road in response to a complaint of a
<u>Dea</u>	dline: N/A		
cons	recommended corrective action deadline date applies to all conditions noted on this retitute non-compliance and/or corrective actions are not completed by the deadline, othering compliance on the above project.		
Insp	pector Signature:		Date: <u>8-15-18</u>



## FIELD INSPECTION PHOTO LOG

Project Name: <u>Mountain Valley Pipeline</u> Date:Wednesday, August 15, 2018

